

Does the cap on your Black Tank Flush keep coming out of inlet?

If it does, you may want to contact your Airstream Dealer and order an upgraded screw in plug to replace the original press fit cap.

Old style press fit cap



*Replacement cap for black tank flush inlet
screw in cap*



Airstream Part Number 601392-01